

Technical Information

DF73



CerDeChromAdvanz – Ceramic Color Management System Seven-Color Printing

Inglaze Colors for the Decoration of Porcelain (lead free)

Firing range: 1200-1220 °C

CerDeChromAdvanz gives us the opportunity of doing the first seven-color printing process in the ceramic industry. The seven-color printing process

enables us to reproduce designs favourably compared to the original design in an economical way.

| Sequence of prints | Color shade | Product no. | Pasting ratio | |
|--|-------------|-----------------|---------------|------------------------------------|
| 1 st print | yellow | 13 855 | 100 : 60 | color : medium 80 820 ¹ |
| 2 nd print | cyan | 12 1916 | 100 : 70 | color : medium 80 820 ¹ |
| 3 rd print | magenta | 77 1910 | 100 : 70 | color : medium 80 820 ¹ |
| Intermediate printing with medium 80 3012 | | | | |
| 4 th print | green | 11 84435 | 100 : 65 | color : medium 80 820 ¹ |
| 5 th print | blue | 12 1910 | 100 : 60 | color : medium 80 820 ¹ |
| 6 th print | red | 17 1917 | 100 : 55 | color : medium 80 820 ¹ |
| 7 th print | black | 14 1910 | 100 : 70 | color : medium 80 820 ¹ |

¹ GHS symbol 05, 09, H phrases 315, 318, 411, EUH019

Screen Printing

The colors are printed best with a polyester screen 120 S (120 mesh/cm or 305 mesh/inch, resp.). For screening, 48 lines per cm are ideal. The screen angle for magenta, green and blue should be 75°, for cyan and red 15° and for yellow and black 45°. The preferred squeegee hardness is 75 - 80 shore. The indicated values for the screen angle are only recommendations according to our experience. These values should, however, be tested under individual processing conditions before use.

Firing

Inglaze for porcelain: 1200-1220 °C (60-90 min)

Resistance

The colors have been tested according to EN 1388.1 and 1388.2 (4 % acetic acid at 22 °C, 24 h). Heavy metal release is far below the official restrictions.

Storage

The colors should be stored in a dry place. In order to ensure that the colors have not absorbed any humidity, we recommend drying the powder colors at approx. 130 °C prior to mixing.

Safety Data Sheets

Our safety data sheets, which are available for every product, provide you with useful advice for working with our products.

Quality

All Ferro products are manufactured according to stringent specifications, and thoroughly tested before leaving our premises. Ferro's quality control procedures are warranted by EN ISO 9001, and certification is carried out annually.

Limitation of Warranty and Liability

Ferro believes that the information contained in this document is accurate at the time of its publication. Ferro makes no warranty with respect to the information contained in this document. The information in this document is not a product specification, either in whole or in part. Your use of the information contained in this document and your purchase and use of this Ferro product are at your sole discretion. Downstream users are responsible for determination of the suitability of this product and for testing in specific applications. Nothing in this document shall be construed as a license for use that infringes upon any property rights of any third party. Please refer to the Safety Data Sheet (SDS) for safe use, handling and disposal information. All sales by Ferro to you are subject to Ferro's Terms and Conditions of Sale, as amended from time to time and available at www.ferro.com. In the event this document conflicts with Ferro's Terms and Conditions of Sale, Ferro's Terms and Conditions of Sale shall control.