

# Technical Information DF12

Performance Colors & Glass

# CerDeChromAdvanz – Ceramic Color Management System Four-Color Printing Onglaze Colors for the Decoration of Porcelain, Bone China, Vitreous China, and Earthenware

Firing Range 780 to 900 °C

Due to the newly developed four-color printing process **CerDeChromAdvanz** analogous to a special four-color separation system it is possible to reproduce designs in an optimal quality.

## **Printing Parameters**

Following printing parameters are recommended:

Screen textile: polyester 120 (305 mesh/inch)

**Screening:** 48 lines per cm / 120 lines per inch (elliptic)

Screen angle: Magenta: 15 °

Cyan: 75 ° Yellow, Black: 45 °

Squeegee hardness: 75 - 80 °shore

The indicated values for the screen angle are only recommendations according to our experience. These values should, however, be tested under individual processing condition before use.

Coating flux 10 169 fits perfectly as a top coat when required. Recommended mixing ration: 10 parts coating flux 10 169 to 10 parts medium 80 3012.

Powder colors should be stored in a dry place. Opened containers should be closed carefully. To ensure that the colors have not absorbed any humidity, we recommend drying the color powder at approx. 130 °C prior to mixing.

Table 1: CerDeChromAdvanz onglaze products for four color printing

Sequence of prints	Color Shade	Product no.	Pasting ratio	
1 <sup>st</sup> print	cyan	12 1522	10:8	color : medium 80 810
2 <sup>na</sup> print	yellow	13 651 <sup>1</sup>	10:8	color : medium 80 810
3 <sup>ra</sup> print	magenta	77 571	10:8	color : medium 80 810
4 <sup>th</sup> print	black	14 209 <sup>1+2</sup>	10:8	color : medium 80 810

<sup>&</sup>lt;sup>1</sup> GHS symbol 07,08,09. H351, 360Df, 372, 410

<sup>&</sup>lt;sup>2</sup> H302 + H332

#### **Firing Conditions**

Normal firing: 780 - 830 °C Fast firing: 850 - 900 °C.

#### Resistance

The colors have been tested according to EN 1388.1 and 1388.2 (4 % acetic acid at 22 °C, 24 h). Heavy metal release is far below the official restriction.

#### **Satety Data Sheets**

Our safety data sheets, which are available for every product, provide you with useful advise for working with our products.

#### Quality

All Ferro products are manufactured according to stringent specifications, and thoroughly tested before leaving our premises. Ferro's quality control procedures are warranted by DIN EN ISO 9001, and certification is carried out annually.

### Limitation of Warranty and Liability

Ferro believes that the information contained in this document is accurate at the time of its publication. Ferro makes no warranty with respect to the information contained in this document. The information in this document is not a product specification, either in whole or in part. Your use of the information contained in this document and your purchase and use of this Ferro product are at your sole discretion. Downstream users are responsible for determination of the suitability of this product and for testing in specific applications. Nothing in this document shall be construed as a license for use that infringes upon any property rights of any third party. Please refer to the Safety Data Sheet (SDS) for safe use, handling and disposal information. All sales by Ferro to you are subject to Ferro's Terms and Conditions of Sale, as amended from time to time and available at www.ferro.com. In the event this document conflicts with Ferro's Terms and Conditions of Sale, Ferro's Terms and Conditions of Sale shall control.